




4 guide chamfers  
4 fasi  
4 Führungsfasen  
4 listels  
4 márgenes  
4 фазы

3584HTA



3584HTA (m7)

Ø mm	1~3	3.1~6	6.1~10	10.1~18	18.1~20
tol. D µ	+12 / +2	+16 / +4	+21 / +6	+25 / +7	+29 / +8



D(m7)	d(h6)	l1	l2	L	Stock
mm 6.60	8	64	76	116	○
6.70	8	64	76	116	○
6.80	8	64	76	116	●
6.90	8	64	76	116	○
7.00	8	64	76	116	●
7.10	8	64	76	116	●
7.20	8	64	76	116	●
7.30	8	64	76	116	○
7.40	8	64	76	116	○
7.50	8	64	76	116	●
7.60	8	64	76	116	○
7.70	8	64	76	116	○
7.80	8	64	76	116	●
7.90	8	64	76	116	○
8.00	8	64	76	116	●
8.10	10	80	95	142	●
8.20	10	80	95	142	●
8.30	10	80	95	142	●
8.40	10	80	95	142	○
8.50	10	80	95	142	●
8.60	10	80	95	142	●
8.70	10	80	95	142	○
8.80	10	80	95	142	●
8.90	10	80	95	142	○
9.00	10	80	95	142	●
9.10	10	80	95	142	●
9.20	10	80	95	142	●
9.30	10	80	95	142	○
9.40	10	80	95	142	○
9.50	10	80	95	142	●
9.60	10	80	95	142	○
9.70	10	80	95	142	○
9.80	10	80	95	142	●
9.90	10	80	95	142	○
10.00	10	80	95	142	●
10.20	12	96	114	163	●

● stock standard ○ non-standard stock ■ stock exhaustion